

Georgetown Flume Photographic Log

Photo Number	Photo Description
090519-B-001	Concrete sampling at Ellis substation pad #1.
090519-B-002	View of sample LC2 subsample locations, looking south.
090519-B-003	View of sample LC1 subsample locations, looking north.
090519-B-004	Location of samples LC1 and LC2 in relation to edge of concrete pad and flume.



Milwaukee
DRILL
1/2" (13 mm)
2/1







HONDA
EU2000i